

Redmond F & R - Station 403 Airport

Desc_fir06A

City of Redmond

| | | | |
|---------------|-------|-----------------|--|
| Building Type | | County | |
| Fire - City | | Deschutes | |
| Street | | | |
| 911 Se Salmon | | | |
| City | State | Zip | |
| Redmond | OR | 97756 | |
| Latitude | | Longitude | |
| 44.25494 | | 121.15803 | |
| Tracking Code | | Inspection Date | |
| Missed | | 9/15/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Redmond F & R - Station 403
Airport

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | 1992 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| | |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| | |
| | |
| | |