

# Buckingham Elementary School

Bend-LaPine SD 1

Desc\_sch03A

Building Type	County	
School	Deschutes	
Street		
62560 Hamby Rd		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.07239	121.24214	
Tracking Code	Inspection Date	
RVS in 2006	7/5/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	3.4	-1.5	-0.5	0	0	-0.6	0	0	0.8
Secondary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	W2	4.8	-3	-0.5	0	1.6	-0.8	0	0	2.1

Buckingham Elementary School

## Final RVS Score

Final Type	Final Score
C2	0.3

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Buckingham Elementary School

Desc\_sch03A

Enrollment 681	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1980
Total Area (square ft) 55376	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
			
E Falling Hazard	NW Plan Irregularity Primary	NW Vertical Irregularity Primary	
			
NW Primary Structural Type	NW General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries