

# LaPine Senior High School

Desc\_sch06A

Bend-LaPine SD 1

Building Type		County	
School		Deschutes	
Street			
51633 Coach Rd			
City	State	Zip	
La Pine	OR	97739	
Latitude		Longitude	
43.68042		121.50696	
Tracking Code		Inspection Date	
RVS in 2006		7/3/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

LaPine Senior High School

## Final RVS Score

Final Type


Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
527		1981	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
100068	1	No	No


Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE General Site

S Other  
addition

SW General Site



SW Plan Irregularity Primary



SW Vertical Irregularity Primary

W General Site  
addition in center

# LaPine Senior High School

Desc\_sch06B

Bend-LaPine SD 1

Building Type		County	
School		Deschutes	
Street			
51633 Coach Rd			
City		State	Zip
La Pine		OR	97739
Latitude		Longitude	
43.67929		121.50706	
Tracking Code		Inspection Date	
RVS in 2006		7/3/2006	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

LaPine Senior High School

## Final RVS Score

Final Type


Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
527		1981	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
100068	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

