

# M A Lynch Elementary School

Redmond SD 2J

Desc\_sch09A

|                    |       |                 |  |
|--------------------|-------|-----------------|--|
| Building Type      |       | County          |  |
| School             |       | Deschutes       |  |
| Street             |       |                 |  |
| 1314 Sw Kalama Ave |       |                 |  |
| City               | State | Zip             |  |
| Redmond            | OR    | 97756           |  |
| Latitude           |       | Longitude       |  |
| 44.26584           |       | 121.18235       |  |
| Tracking Code      |       | Inspection Date |  |
| RVS in 2006        |       | 6/29/2006       |  |



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 3.6         | -2         | -0.5       | 0        | 0          | 0      | 0      | 0      | 1.1       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

M A Lynch Elementary School

## Final RVS Score

Final Type

Final Score

RM1

1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
| 571                    | 1965                        | 1965                     | 1960               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
| 42736                  | 1                           | No                       | No                 |

|  |   |
|--|---|
| Plan Irregularities                              | Vertical Irregularities   |
| Reentrant Corners: Other (Adjacent Build/Entity) | Steps in Elevation View: Single Change                            |
| None   | Steps in Elevation View: Single Change (Adjacent Building/Entity) |
| None   | None  |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |



E Plan Irregularity Primary



S Primary Structural Type

# M A Lynch Elementary School

Redmond SD 2J

Desc\_sch09B

|                    |       |                 |  |
|--------------------|-------|-----------------|--|
| Building Type      |       | County          |  |
| School             |       | Deschutes       |  |
| Street             |       |                 |  |
| 1314 Sw Kalama Ave |       |                 |  |
| City               | State | Zip             |  |
| Redmond            | OR    | 97756           |  |
| Latitude           |       | Longitude       |  |
| 44.26544           |       | 121.18235       |  |
| Tracking Code      |       | Inspection Date |  |
| RVS in 2006        |       | 6/29/2006       |  |



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 3.6         | -2         | -0.5       | 0        | 0          | 0      | 0      | 0      | 1.1       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

M A Lynch Elementary School

## Final RVS Score

Final Type

Final Score

RM1

1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
| 571                    |                             | 1965                     | 1980               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
| 42736                  | 1                           | No                       | No                 |

|   |   |
|---|---|
| Plan Irregularities                             | Vertical Irregularities   |
| Reentrant Corners:Other (Adjacent Build/Entity) | Steps in Elevation View: Single Change                            |
| None  | Steps in Elevation View: Single Change (Adjacent Building/Entity) |
| None  | None  |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |



SW Vertical Irregularity Primary

