

Elk Meadow Elementary School

Desc_sch18A

Bend-LaPine SD 1

Building Type		County	
School		Deschutes	
Street			
60880 Brookwood Blvd			
City	State	Zip	
Bend	OR	97702	
Latitude		Longitude	
44.01438		121.34527	
Tracking Code		Inspection Date	
RVS in 2006		7/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Elk Meadow Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
576	1993	1993	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
62000	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Large Diaphragm or Central Opening	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Plan Irregularity Primary



S Plan Irregularity Secondary



N Vertical Irregularity Primary

