


# Sky View Middle School

Bend-LaPine SD 1

Desc\_sch24A

Building Type School	County Deschutes	
Street 63555 Ne 18th St		
City Bend	State OR	Zip 97701
Latitude 44.10746	Longitude 121.28014	
Tracking Code New Building	Inspection Date 9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sky View Middle School

### Final RVS Score

Final Type	Final Score

### FEMA-154 Collapse Potential

Low (<1%)

# Sky View Middle School

Desc\_sch24A

Enrollment 600	Year Built (Field Verified) 2000	Year Built (Alt. Source) 2000	Est. Decade Built
Total Area (square ft) 113000	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries