

Ed. Skills Building

Umpqua CC

Doug_coc02A

Building Type Community_College	County Douglas	
Street 1140 Umpqua College Rd		
City Roseburg	State OR	Zip 97470
Latitude 43.29086	Longitude 123.33223	
Tracking Code Miller 2004-05	Inspection Date 7/20/2004	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	-2.4	0	0	0	-1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Ed. Skills Building

Final RVS Score

Final Type	Final Score
W2	-1.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ed. Skills Building

Doug_coc02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1979	1979	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10813	1	No	No
Plan Irregularities		Vertical Irregularities	
Yes: Unknown		None	
Falling Hazards		Poor Conditions	
None			
None			
None			



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries