

# Gym/PE Complex

Umpqua CC

Doug\_coc06A

Building Type		County	
Community_College		Douglas	
Street			
1140 Umpqua College Rd			
City	State	Zip	
Roseburg	OR	97470	
Latitude		Longitude	
43.29165		123.33387	
Tracking Code		Inspection Date	
Miller 2004-05		7/20/2004	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0		0	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Gym/PE Complex

## Final RVS Score

Final Type


Final Score

PC1

2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Gym/PE Complex

Doug\_coc06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1970	1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
17068	1	No	No

Plan Irregularities	Vertical Irregularities
None	None

Falling Hazards	Poor Conditions
None	
None	
None	



S General Site

