

# Reedsport FD Station 1

City of Reedsport

Doug\_fir14A

Building Type	County
Fire - City	Douglas
Street	
124 N 4th St	
City	State Zip
Reedsport	OR 97467
Latitude	Longitude
43.70179	124.09687
Tracking Code	Inspection Date
RVS in 2006	8/18/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Reedsport FD Station 1

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reedsport FD Station 1

Doug\_fir14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Vertical Change in Structural Type (Soft over Stiff)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None			
			
NW Elevation View		SE Plan Irregularity Secondary	
		Large openings, the back wall of this garage is solid RM indicating a potential Torsion problem.	
			
SE Secondary Structural Type RM walls make a 'C' shape.		NE Plan Irregularity Primary Out of plane lateral system and an elevation step.	
		E Primary Structural Type and secondary structure type, RM on the bot. garage wall and W2 above.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries