

Fair Oaks RFPD

Doug_fir16A

Fair Oaks RFPD

Building Type		County	
Fire - RFPD		Douglas	
Street			
6522 Nonpareil Rd			
City	State	Zip	
Sutherlin	OR	97479	
Latitude		Longitude	
43.40935		123.20078	
Tracking Code		Inspection Date	
RVS in 2006		8/11/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fair Oaks RFPD

Final RVS Score

Final Type

Final Score

S3

2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	Other
None	None
None	None



E Poor Condition
fire damage



S Poor Condition
fire damage



SE Elevation View



SW Elevation View



N Plan Irregularity Primary
backwall solid indicating torsion problem



S General Site

