

Scottsburg RFPD

Scottsburg RFPD

Doug_fir36A

| | | |
|------------------------------|------------------------------|--------------|
| Building Type Fire - RFPD | County Douglas | |
| Street 33237 State Hwy 38 | | |
| City Scottsburg | State OR | Zip 97473 |
| Latitude 43.67488 | Longitude 123.80415 | |
| Tracking Code RVS in 2006 | Inspection Date 8/18/2006 | |



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | 0 | -0.5 | 0 | 0 | -0.4 | 0 | 0 | 2.9 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Scottsburg RFPD

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 2.9 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|--|-----------------------------|---|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1970 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| Torsion: Eccentric Stiffness | | None | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  N Elevation View | |  W Plan Irregularity Primary | |
| | |  SE Elevation View | |

