

# Gardiner RFPD

Gardiner RFPD

Doug\_fir39A

Building Type Fire - RFPD	County Douglas	
Street 208 Marsh St		
City Gardiner	State OR	Zip 97441
Latitude 43.7321	Longitude 124.11077	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Gardiner RFPD

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

High (>10%)



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE General Site		E Plan Irregularity Primary	
		SW Plan Irregularity Primary	
			
NE Other			
<p>no torsion due to section extending from the wall the bays are on.</p>			

