

North Douglas Fire & EMS - Station #6

North Douglas County Fire & EMS

Doug_fir44A

Building Type	County	
Fire - RFPD	Douglas	
Street		
4821 Goodrich Hwy		
City	State	Zip
Oakland	OR	97462
Latitude	Longitude	
43.50256	123.29264	
Tracking Code	Inspection Date	
RVS in 2006	8/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	0	0	0	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Douglas Fire & EMS - Station #6

Final RVS Score

Final Type	Final Score
W1	3.9

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Douglas Fire & EMS - Station #6

Doug_fir44A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Plan Irregularity Primary back wall is solid indicating a possible torsion problem.			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries