

Douglas County Sheriff's Office

Douglas County

Doug_pol01A

Building Type Police - County	County Douglas	
Street 680 Fir Ave		
City Reedsport	State OR	Zip 97467
Latitude 43.70116	Longitude 124.1005	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	0	0	0	0	-0.6	0	1.2
Secondary	C1	2.5	-1.5	0	0	0	0	-0.6	0	0.4
Tertiary	S3	3.2	0	0	0	0	0	-0.6	0	2.6

Douglas County Sheriff's Office

Final RVS Score

Final Type	Final Score
C1	0.4

FEMA-154 Collapse Potential

High (>10%)



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Douglas County Sheriff's Office

Doug_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1969	1969	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change	
None		Internal Discontinuous Diaphragm (large internal opening)	
None		Vertical Change in Structural Type (Soft over Stiff)	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	
			
S	Falling Hazard	S	Vertical Irregularity Primary raised S3 section that gives the building increased head height through the center of the building. Thus, this irregularity also creates a large ope
			
W	Elevation View	N	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries