

# Sutherlin Police Dept

City of Sutherlin

Doug\_pol07A

Building Type Police - City	County Douglas	
Street 126 E Central Ave		
City Sutherlin	State OR	Zip 97479
Latitude 43.39005	Longitude 123.312	
Tracking Code RVS in 2006	Inspection Date 8/11/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	URM	1.8	-1	-0.5	0	0	0	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Sutherlin Police Dept

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Sutherlin Police Dept

Doug\_pol07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		None	
Out of Plane Lateral-Force-Resistance Elements		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Primary Structural Type	E	Vertical Irregularity Primary
			
S	Vertical Irregularity Primary		
			
SE	Plan Irregularity Secondary reentrant corner due to adjacent building.	NW	Plan Irregularity Tertiary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries