

Reedsport Police Dept

City of Reedsport

Doug_pol08A

Building Type	County
EOC-Public Safety Answering P	Douglas
Street	
146 N 4th St	
City	State Zip
Reedsport	OR 97467
Latitude	Longitude
43.70179	124.09687
Tracking Code	Inspection Date
RVS in 2006	8/18/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Reedsport Police Dept

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Reedsport Police Dept

Doug_pol08A

Enrollment 291	Year Built (Field Verified) 	Year Built (Alt. Source) 	Est. Decade Built 1950
Total Area (square ft) 	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness None		Vertical Change in Structural Type (Soft over Stiff) None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Elevation View		SE Plan Irregularity Secondary	
			
SE Secondary Structural Type RM walls on the sides and back of the garage form a "C" shape indicating a potential torsion problem.		NE Plan Irregularity Primary out of plane lateral system and elevation step.	
		E Primary Structural Type and secondary structure: RM wall on the edge of the garage wall and a W2 wall above.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries