

Douglas County Sheriff's Office and ERC - 911

Doug_pol10A

Douglas County

Building Type	County	
EOC-Public Safety Answering P	Douglas	
Street		
1036 SE Douglas St		
City	State	Zip
Roseburg	OR	97470
Latitude	Longitude	
43.21119	123.3408	
Tracking Code	Inspection Date	
RVS in 2006	8/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S4	3.2	-1	-0.5	0	0	-0.4	0	0	1.3
Secondary	C2	3.2	-1	-0.5	0	0	-0.4	0	0	1.3
Tertiary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1

Douglas County Sheriff's Office and ERC - 911

Final RVS Score

Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Douglas County Sheriff's Office and ERC - 911

Doug_pol10A

Enrollment 210	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1970		
Total Area (square ft) 	Number of Stories 4	Basement	Pounding Potential No		
Plan Irregularities Reentrant Corners: Other Reentrant Corners: Other (Adjacent Build/Entity) None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Internal Discontinuous Diaphram (large internal opening)			
Falling Hazards Heavy Cladding (thick stone or concrete) None None		Poor Conditions None None None			
	SE General Site		NE Plan Irregularity Primary steps in elevation also		SW Vertical Irregularity Primary
	NW General Site				



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries