

# Eastwood Elementary School

Douglas County SD 4

Doug\_sch01A

|                              |                              |              |
|------------------------------|------------------------------|--------------|
| Building Type<br>School      | County<br>Douglas            |              |
| Street<br>2550 Se Waldon Ave |                              |              |
| City<br>Roseburg             | State<br>OR                  | Zip<br>97470 |
| Latitude<br>43.2077          | Longitude<br>123.32039       |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>1/29/2007 |              |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 2.8       |
| Secondary | C2   | 2.8         | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 2.8       |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |


Eastwood Elementary School

### Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | 2.8         |

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Eastwood Elementary School

Doug\_sch01A

|  |                                     |   |                           |
|--|-------------------------------------|---|---------------------------|
| Enrollment<br>337  | Year Built (Field Verified)<br>1957 | Year Built (Alt. Source)<br>1957  | Est. Decade Built<br>1950 |
| Total Area (square ft)<br>31898  | Number of Stories<br>1              | Basement  | Pounding Potential<br>No  |
| Plan Irregularities<br>None<br>None<br>None  |                                     | Vertical Irregularities<br>Steps in Elevation View: Single Change<br>None<br>None   |                           |
| Falling Hazards<br>Other: Ornamental Hazard Over Exit<br>None<br>None                |                                     | Poor Conditions<br>None<br>None<br>None   |                           |
|    |                                     |   |                           |
| NW Falling Hazard  |                                     | NW Secondary Structural Type  |                           |
|  |                                     | SW Vertical Irregularity Primary  |                           |
|   |                                     |  |                           |
| S Primary Structural Type  |                                     | SE Elevation View   |                           |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Eastwood Elementary School

Douglas County SD 4

Doug\_sch01B

|                              |                              |              |
|------------------------------|------------------------------|--------------|
| Building Type<br>School      | County<br>Douglas            |              |
| Street<br>2550 SE Waldon Ave |                              |              |
| City<br>Roseburg             | State<br>OR                  | Zip<br>97470 |
| Latitude<br>43.20769         | Longitude<br>123.31978       |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>1/29/2007 |              |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | -1         | 0          | 0        | 0          | 0      | 0      | 0      | 1.8       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Eastwood Elementary School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | 1.8         |

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Eastwood Elementary School

Doug\_sch01B

|  |                                     |   |                             |  |                  |
|--|-------------------------------------|---|-----------------------------|--|------------------|
| Enrollment<br>337  | Year Built (Field Verified)<br>1957 | Year Built (Alt. Source)<br>1957  | Est. Decade Built<br>1960   |  |                  |
| Total Area (square ft)<br>31898  | Number of Stories<br>1              | Basement  | Pounding Potential<br>No    |  |                  |
| Plan Irregularities  |                                     | Vertical Irregularities   |                             |  |                  |
| Out of Plane Lateral-Force-Resistance Elements                                     |                                     | Steps in Elevation View: Single Change  |                             |  |                  |
| Large Diaphragm or Central Opening   |                                     | None  |                             |  |                  |
| None   |                                     | None  |                             |  |                  |
| Falling Hazards  |                                     | Poor Conditions   |                             |  |                  |
| Other: Ornamental Hazard Over Exit   |                                     | None  |                             |  |                  |
| None   |                                     | None  |                             |  |                  |
| None   |                                     | None  |                             |  |                  |
|  | S Primary Structural Type           |  | S Plan Irregularity Primary |  | E Elevation View |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Eastwood Elementary School

Douglas County SD 4

Doug\_sch01C

|                              |                              |              |
|------------------------------|------------------------------|--------------|
| Building Type<br>School      | County<br>Douglas            |              |
| Street<br>2550 SE Waldon Ave |                              |              |
| City<br>Roseburg             | State<br>OR                  | Zip<br>97470 |
| Latitude<br>43.2081          | Longitude<br>123.31972       |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>1/29/2007 |              |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W2   | 3.8         | 0          | 0          | 0        | 2.4        | 0      | 0      | 0      | 6.2       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Eastwood Elementary School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2         | 6.2         |

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Eastwood Elementary School

Doug\_sch01C

|   |                                     |  |                           |
|---|-------------------------------------|--|---------------------------|
| Enrollment<br>337   | Year Built (Field Verified)<br>1957 | Year Built (Alt. Source)<br>1957   | Est. Decade Built<br>1990 |
| Total Area (square ft)<br>31898   | Number of Stories<br>1              | Basement   | Pounding Potential<br>No  |
| Plan Irregularities<br>None<br>None<br>None   |                                     | Vertical Irregularities<br>None<br>None<br>None  |                           |
| Falling Hazards<br>Other: Ornamental Hazard Over Exit   |                                     | Poor Conditions<br>None<br>None<br>None  |                           |
| <br>E Primary Structural Type |                                     | <br>NW Elevation View |                           |



**OregonGeology**

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Eastwood Elementary School

Douglas County SD 4

Doug\_sch01D

|                              |                              |              |
|------------------------------|------------------------------|--------------|
| Building Type<br>School      | County<br>Douglas            |              |
| Street<br>2550 SE Waldon Ave |                              |              |
| City<br>Roseburg             | State<br>OR                  | Zip<br>97470 |
| Latitude<br>43.20824         | Longitude<br>123.32035       |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>1/29/2007 |              |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | -1         | -0.5       | 0        | 0          | 0      | 0      | 0      | 1.3       |
| Secondary | W2   | 3.8         | -2         | -0.5       | 0        | 0          | 0      | 0      | 0      | 1.3       |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Eastwood Elementary School

### Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | 1.3         |

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Eastwood Elementary School

Doug\_sch01D

|  |                                     |   |                           |
|--|-------------------------------------|---|---------------------------|
| Enrollment<br>337  | Year Built (Field Verified)<br>1957 | Year Built (Alt. Source)<br>1957  | Est. Decade Built<br>1960 |
| Total Area (square ft)<br>31898  | Number of Stories<br>1              | Basement  | Pounding Potential<br>No  |
| Plan Irregularities<br>Reentrant Corners: Other<br>None<br>None                      |                                     | Vertical Irregularities<br>Steps in Elevation View: 2 to 3 Changes<br>None<br>None    |                           |
| Falling Hazards<br>None<br>None<br>None  |                                     | Poor Conditions<br>None<br>None<br>None   |                           |
|    |                                     |    |                           |
| N Plan Irregularity Primary  |                                     | NE Primary Structural Type  |                           |
|  |                                     | NW Secondary Structural Type  |                           |
|   |                                     |   |                           |
| E Plan Irregularity Primary  |                                     | SE Vertical Irregularity Primary  |                           |
|  |                                     |  |                           |
|  |                                     | NW Elevation View   |                           |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries