

# Fullerton IV Elementary School

Douglas County SD 4

Doug\_sch03A

Building Type	County	
School	Douglas	
Street		
2560 W Bradford Ave		
City	State	Zip
Roseburg	OR	97470
Latitude	Longitude	
43.21711	123.38154	
Tracking Code	Inspection Date	
RVS in 2006	8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fullerton IV Elementary School

## Final RVS Score

Final Type	Final Score
W1	4.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Fullerton IV Elementary School

Doug\_sch03A

Enrollment 346	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1960
Total Area (square ft) 31921	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Elevation View		 N Other <p>This building is attached to "B." The attachment however is really only holding the covered walkway. We did not specify an irregularity due to an ad</p>	

# Fullerton IV Elementary School

Douglas County SD 4

Doug\_sch03B

Building Type	County	
School	Douglas	
Street		
2560 W Bradford Ave		
City	State	Zip
Roseburg	OR	97470
Latitude	Longitude	
43.21747	123.38126	
Tracking Code	Inspection Date	
RVS in 2006	8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Tertiary		0	0	0	0	0	0	0	0	0

Fullerton IV Elementary School

## Final RVS Score

Final Type	Final Score
RM1	1.9

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Fullerton IV Elementary School

Doug\_sch03B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
346		1961	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
31921	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



NE Secondary Structural Type



NW Plan Irregularity Primary



NW Primary Structural Type



N Plan Irregularity Primary



E Secondary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Fullerton IV Elementary School

Douglas County SD 4

Doug\_sch03C

Building Type	County	
School	Douglas	
Street		
2560 W Bradford Ave		
City	State	Zip
Roseburg	OR	97470
Latitude	Longitude	
43.21716	123.38192	
Tracking Code	Inspection Date	
RVS in 2006	8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Fullerton IV Elementary School

## Final RVS Score

Final Type	Final Score
RM1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Fullerton IV Elementary School

Doug\_sch03C

Enrollment 346	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1960
Total Area (square ft) 31921	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements None		Steps in Elevation View: Single Change Vertical Change in Structural Type (Soft over Stiff) None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys None		None	
None		None	
			
N Primary Structural Type and secondary		S Vertical Irregularity Primary	
		W Falling Hazard Reinforced chimney? and out-of-plane offset	