

Rose Elementary School

Douglas County SD 4

Doug_sch06A

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Douglas | |
| Street 948 SE Roberts Ave | | |
| City Roseburg | State OR | Zip 97470 |
| Latitude 43.20159 | Longitude 123.34906 | |
| Tracking Code RVS in 2006 | Inspection Date 8/26/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | -1 | 0 | 0 | 0 | 0 | 0.3 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Rose Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 0.3 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rose Elementary School

Doug_sch06A

| | | | |
|--|---|---|---|
| Enrollment 227 | Year Built (Field Verified) 1939 | Year Built (Alt. Source) 1939 | Est. Decade Built 1940 |
| Total Area (square ft) 38034 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None | | Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None | |
| Falling Hazards Unreinforced Chimneys None None | | Poor Conditions None None None | |
|  |  |  | <p>NW Falling Hazard chimney reinforced?</p> <p>SW General Site</p> <p>S Plan Irregularity Primary step in elevation also</p> |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rose Elementary School

Douglas County SD 4

Doug_sch06B

| | | |
|--------------------|-----------------|-------|
| Building Type | County | |
| School | Douglas | |
| Street | | |
| 948 SE Roberts Ave | | |
| City | State | Zip |
| Roseburg | OR | 97470 |
| Latitude | Longitude | |
| 43.20168 | 123.34864 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 8/26/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Secondary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Tertiary | RM1 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |

Rose Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 1.3 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rose Elementary School

Doug_sch06B

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 227 | Year Built (Field Verified) 1939 | Year Built (Alt. Source) 1939 | Est. Decade Built 1970 |
| Total Area (square ft) 38034 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Building On Hill or Sloped Site | |
| Reentrant Corners: Other (Adjacent Build/Entity) | | Steps in Elevation View: Very Irregular Changes | |
| None | | Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent) | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| SW Plan Irregularity Primary step in elevation also | | SE General Site | |
|  | | NE Vertical Irregularity Secondary reentrant corner also | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries