

Joseph Lane Middle School

Douglas County SD 4

Doug_sch09A

| | | | |
|-----------------|-------|-----------------|--|
| Building Type | | County | |
| School | | Douglas | |
| Street | | | |
| 2153 NE Vine St | | | |
| City | State | Zip | |
| Roseburg | OR | 97470 | |
| Latitude | | Longitude | |
| 43.23586 | | 123.34636 | |
| Tracking Code | | Inspection Date | |
| RVS in 2006 | | 8/25/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Joseph Lane Middle School

Final RVS Score

Final Type

Final Score

W2

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 829 | | 1955 | 1950 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 91990 | 1 | Yes | No |

| | |
|--|---|
| Plan Irregularities | Vertical Irregularities |
| Reentrant Corners: Other | Steps in Elevation View: Very Irregular Changes |
| Non-Parallel System | Building On Hill or Sloped Site |
| Out of Plane Lateral-Force-Resistance Elements | None |


| | |
|-----------------------|-----------------|
| Falling Hazards | Poor Conditions |
| Unreinforced Chimneys | None |
| None | None |
| None | None |



W General Site



W Plan Irregularity Tertiary

W Falling Hazard
reinforced chimney?

N General Site

N Plan Irregularity Primary
steps in elevation alsoSW Vertical Irregularity Primary
reentrant corner also