

Glide Elementary School

Glide SD 12

Doug_sch11A

Building Type	County	
School	Douglas	
Street		
1477 Glide Loop Dr		
City	State	Zip
Glide	OR	97443
Latitude	Longitude	
43.30735	123.08665	
Tracking Code	Inspection Date	
RVS in 2006	8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Glide Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Glide Elementary School

Doug_sch11A

Enrollment 349	Year Built (Field Verified) 1963	Year Built (Alt. Source) 1963	Est. Decade Built 1960
Total Area (square ft) 52180	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW Plan Irregularity Primary		N Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Glide Elementary School

Doug_sch11B

Glide SD 12

Building Type	County	
School	Douglas	
Street		
1477 Glide Loop Dr		
City	State	Zip
Glide	OR	97443
Latitude	Longitude	
43.30742	123.08578	
Tracking Code	Inspection Date	
RVS in 2006	8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0

Glide Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Glide Elementary School

Doug_sch11B

Enrollment 349	Year Built (Field Verified) 1963	Year Built (Alt. Source) 1963	Est. Decade Built 1960
Total Area (square ft) 52180	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>NE Vertical Irregularity Primary and reentrant corner.</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries