

# Canyonville School

South Umpqua SD 19

Doug\_sch13A

Building Type		County	
School		Douglas	
Street			
124 N Main St			
City	State	Zip	
Canyonville	OR	97417	
Latitude		Longitude	
42.9281		123.28035	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canyonville School

## Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
210		1935	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33050	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: Other	None
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	Open cracks in structural members
None	None
None	None



N Poor Condition



SW Plan Irregularity Primary

SW Falling Hazard  
reinforced?

S Elevation View

# Canyonville School

South Umpqua SD 19

Doug\_sch13B

Building Type		County	
School		Douglas	
Street			
124 N Main St			
City	State	Zip	
Canyonville	OR	97417	
Latitude		Longitude	
42.92807		123.28052	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canyonville School

## Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
210		1935	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33050	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



# Canyonville School

South Umpqua SD 19

Doug\_sch13C

Building Type		County	
School		Douglas	
Street			
124 N Main St			
City	State	Zip	
Canyonville	OR	97417	
Latitude		Longitude	
42.92783		123.28057	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canyonville School

## Final RVS Score

Final Type

Final Score

RM1

2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
210		1935	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33050	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	Cracks
None	None
None	None



SW Elevation View



S Primary Structural Type



SW Poor Condition



# Canyonville School

South Umpqua SD 19

Doug\_sch13D

Building Type		County	
School		Douglas	
Street			
124 N Main St			
City	State	Zip	
Canyonville	OR	97417	
Latitude		Longitude	
42.92807		123.28086	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canyonville School

## Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
210		1935	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33050	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Non-Parallel System	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Vertical Irregularity Primary  
and reentrant corner



N Vertical Irregularity Primary



SE Plan Irregularity Secondary