

# Riddle High School

Riddle SD 70

Doug\_sch21A

Building Type School	County Douglas	
Street 127 Main St		
City Riddle	State OR	Zip 97469
Latitude 42.94897	Longitude 123.36365	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riddle High School

## Final RVS Score

Final Type	Final Score
C2	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riddle High School

Doug\_sch21A

Enrollment 223	Year Built (Field Verified) 1935	Year Built (Alt. Source) 1930	Est. Decade Built 1930		
Total Area (square ft) 49600	Number of Stories 2	Basement	Pounding Potential No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)			
Out of Plane Lateral-Force-Resistance Elements		None			
Reentrant Corners: Other (Adjacent Build/Entity)		None			
Falling Hazards		Poor Conditions			
Unreinforced Chimneys		None			
None		None			
None		None			
	W Plan Irregularity Secondary		E Falling Hazard		E Plan Irregularity Primary
	NE Primary Structural Type		S Plan Irregularity Tertiary step in elevation with adjacent bldg		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riddle High School

Riddle SD 70

Doug\_sch21B

Building Type	County	
School	Douglas	
Street		
127 Main St		
City	State	Zip
Riddle	OR	97469
Latitude	Longitude	
42.94916	123.3633	
Tracking Code	Inspection Date	
RVS in 2006	8/30/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riddle High School

## Final RVS Score

Final Type	Final Score
RM1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Riddle High School

Doug\_sch21B

Enrollment 223	Year Built (Field Verified) 1935	Year Built (Alt. Source) 1935	Est. Decade Built 1950
Total Area (square ft) 49600	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Plan Irregularity Primary		S Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riddle High School

Riddle SD 70

Doug\_sch21C

Building Type School	County Douglas	
Street 127 Main St		
City Riddle	State OR	Zip 97469
Latitude 42.94899	Longitude 123.36289	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riddle High School

## Final RVS Score

Final Type	Final Score
RM1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Riddle High School

Doug\_sch21C

Enrollment 223	Year Built (Field Verified) 1935	Year Built (Alt. Source) 1935	Est. Decade Built 1950
Total Area (square ft) 49600	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None		Vertical Irregularities Steps in Elevation View: Single Change Building On Hill or Sloped Site None	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	
			
N Plan Irregularity Primary		S Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riddle High School

Riddle SD 70

Doug\_sch21D

Building Type School	County Douglas	
Street 127 Main St		
City Riddle	State OR	Zip 97469
Latitude 42.94948	Longitude 123.36322	
Tracking Code RVS in 2006	Inspection Date 9/1/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riddle High School

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Riddle High School

Doug\_sch21D

Enrollment 223	Year Built (Field Verified) 1935	Year Built (Alt. Source) 1935	Est. Decade Built 1970
Total Area (square ft) 49600	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N    Vertical Irregularity Primary reentrant corner as well			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries