

Glendale High School

Glendale SD 77

Doug_sch23A

Building Type	County	
School	Douglas	
Street		
10598 Azalea Glen Rd		
City	State	Zip
Glendale	OR	97442
Latitude	Longitude	
42.74395	123.41455	
Tracking Code	Inspection Date	
RVS in 2006	8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Glendale High School

Final RVS Score

Final Type	Final Score
W2	3.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Glendale High School

Doug_sch23A

Enrollment 235	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1980
Total Area (square ft) 54626	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	
			
W	Plan Irregularity Secondary	NW	Plan Irregularity Primary
			
N	Plan Irregularity Primary		
			
S	Falling Hazard		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Glendale High School

Glendale SD 77

Doug_sch23B

Building Type School	County Douglas	
Street 10598 Azalea Glen Rd		
City Glendale	State OR	Zip 97442
Latitude 42.74397	Longitude 123.41526	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Glendale High School

Final RVS Score

Final Type	Final Score
W1	6.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Glendale High School

Doug_sch23B

Enrollment 235	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1980
Total Area (square ft) 54626	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards Heavy Cladding (thick stone or concrete) None None		Poor Conditions None None None	
 S Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Building Type	County	
School	Douglas	
Street		
10598 Azalea Glen Rd		
City	State	Zip
Glendale	OR	97442
Latitude	Longitude	
42.74398	123.41373	
Tracking Code	Inspection Date	
RVS in 2006	8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Glendale High School

Final RVS Score

Final Type	Final Score
W1	6.3

FEMA-154 Collapse Potential

Low (<1%)



Glendale High School

Doug_sch23C

Enrollment 235	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1980
Total Area (square ft) 54626	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards Heavy Cladding (thick stone or concrete) None None		Poor Conditions None None None	
 W Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Glendale High School

Glendale SD 77

Doug_sch23D

Building Type School	County Douglas	
Street 10598 Azalea Glen Rd		
City Glendale	State OR	Zip 97442
Latitude 42.74398	Longitude 123.41328	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Glendale High School

Final RVS Score

Final Type	Final Score
W1	6.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Glendale High School

Doug_sch23D

Enrollment 235	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1980
Total Area (square ft) 54626	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities None None None	
Falling Hazards Heavy Cladding (thick stone or concrete) None None		Poor Conditions None None None	
 NE General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries