

Highland Elementary School

Reedsport SD 105

Doug_sch24A

Building Type	County
School	Douglas
Street	
2605 Longwood Dr	
City	State Zip
Reedsport	OR 97467
Latitude	Longitude
43.69217	124.12887
Tracking Code	Inspection Date
RVS in 2006	8/18/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1

Highland Elementary School

Final RVS Score

Final Type	Final Score
C2	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Highland Elementary School

Doug_sch24A

Enrollment 356	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1950
Total Area (square ft) 64000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Vertical Change in Structural Type (Soft over Stiff) None	
Falling Hazards None None None		Poor Conditions None None None	
 N Plan Irregularity Primary		 N Primary Structural Type and secondary structural type	 NW Primary Structural Type and secondary structural type
 W Plan Irregularity Primary		 NW Vertical Irregularity Primary	 NW Tertiary Structural Type S3 on the upper portion of this building.
 SE Plan Irregularity Primary		 SE Plan Irregularity Primary	 SE Field Verified Year Built



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



SE General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries