

McGovern Elementary School

Winston-Dillard SD 116

Doug_sch35A

Building Type School	County Douglas	
Street 600 NW Elwood St		
City Winston	State OR	Zip 97496
Latitude 43.12187	Longitude 123.42321	
Tracking Code RVS in 2006	Inspection Date 8/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

McGovern Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

McGovern Elementary School

Doug_sch35A

Enrollment 254	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 55417	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			<p>NE Vertical Irregularity Primary and reentrant corner</p> <p>E General Site</p> <p>S Vertical Irregularity Primary</p>

McGovern Elementary School

Winston-Dillard SD 116

Doug_sch35B

Building Type	County	
School	Douglas	
Street		
600 NW Elwood St		
City	State	Zip
Winston	OR	97496
Latitude	Longitude	
43.1214	123.42356	
Tracking Code	Inspection Date	
RVS in 2006	8/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

McGovern Elementary School

Final RVS Score

Final Type	Final Score
W2	2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

McGovern Elementary School

Doug_sch35B

Enrollment 254	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1959	Est. Decade Built 1960
Total Area (square ft) 55417	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries