

Lookingglass Elementary School

Winston-Dillard SD 116

Doug_sch38A

Building Type		County	
School		Douglas	
Street			
7421 Lookingglass Rd			
City	State	Zip	
Roseburg	OR	97470	
Latitude		Longitude	
43.17792		123.48716	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lookingglass Elementary School

Final RVS Score

Final Type

Final Score

W2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lookingglass Elementary School

Doug_sch38A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
181		1924	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38700	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	Cracks
None	None
None	None




NW Plan Irregularity Primary and also elevation step

N Poor Condition



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lookingglass Elementary School

Winston-Dillard SD 116

Doug_sch38B

Building Type		County	
School		Douglas	
Street			
7421 Lookingglass Rd			
City	State	Zip	
Roseburg	OR	97470	
Latitude		Longitude	
43.17745		123.48731	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lookingglass Elementary School

Final RVS Score

Final Type

Final Score

W2

3.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
181		1924	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38700	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Elevation View
new addition