

Lincoln Middle School

Oakland SD 1

Doug_sch39A

Building Type	County	
School	Douglas	
Street		
931 Old Town Loop Rd		
City	State	Zip
Oakland	OR	97462
Latitude	Longitude	
43.43061	123.29841	
Tracking Code	Inspection Date	
RVS in 2006	8/11/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Middle School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



Lincoln Middle School

Doug_sch39A

Enrollment 170	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1953	Est. Decade Built 1950
Total Area (square ft) 27846	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: Brick Veneer		None	
None		None	
			
E Falling Hazard		NE Primary Structural Type	
		N Plan Irregularity Primary	
		SW Plan Irregularity Secondary	

Lincoln Middle School

Oakland SD 1

Doug_sch39B

Building Type	County
School	Douglas
Street	
931 Old Town Loop Rd	
City	State Zip
Oakland	OR 97462
Latitude	Longitude
43.43075	123.2988
Tracking Code	Inspection Date
RVS in 2006	8/11/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Middle School

Final RVS Score

Final Type	Final Score
W2	3.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Lincoln Middle School

Doug_sch39B

Enrollment 170	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1953	Est. Decade Built 1960
Total Area (square ft) 27846	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 NW Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries