

# Condon High School

Condon SD 25J

Gill\_sch01A

Building Type School	County Gilliam	
Street 210 E Bayard St		
City Condon	State OR	Zip 97823
Latitude 45.2318	Longitude 120.18258	
Tracking Code RVS in 2006	Inspection Date 8/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Condon High School

## Final RVS Score

Final Type	Final Score
W2	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



# Condon High School

Gill\_sch01A

Enrollment 72	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 34000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: Light Cladding		None	
None		None	
None		None	



NE Primary Structural Type



N Building Name



NW Plan Irregularity Primary



W Primary Structural Type



W Primary Structural Type  
WOOD SIDING BENEATH STUCCO



N Elevation View  
W WING



NW Elevation View



W Vertical Irregularity Secondary



SE Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



E Plan Irregularity Primary



# Condon High School

Condon SD 25J

Gill\_sch01B

Building Type School	County Gilliam	
Street 210 E Bayard St		
City Condon	State OR	Zip 97823
Latitude 45.23142	Longitude 120.18261	
Tracking Code RVS in 2006	Inspection Date 8/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Condon High School

## Final RVS Score

Final Type	Final Score
W2	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Condon High School

Gill\_sch01B

Enrollment 72	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1970
Total Area (square ft) 34000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Light Cladding None None		Poor Conditions None None None	
 SE Elevation View		 E Building Name	
 E General Site CONN TO A		 SE General Site CONN TO A	