

# John Day Fire Department

City of John Day

Gran\_fir05A

Building Type	County
Fire - City	Grant
Street	
209 SE Dayton	
City	State Zip
John Day	OR 97845
Latitude	Longitude
44.41431	118.95243
Tracking Code	Inspection Date
RVS in 2006	7/27/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Tertiary		0	0	0	0	0	0	0	0	0


John Day Fire Department

## Final RVS Score

Final Type	Final Score
RM1	-0.5

## FEMA-154 Collapse Potential

Very High (100%)



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# John Day Fire Department

Gran\_fir05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Building On Hill or Sloped Site	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Plan Irregularity Primary		NW Vertical Irregularity Tertiary	
		SW Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# John Day Fire Department

City of John Day

Gran\_fir05B

Building Type	County
Fire - City	Grant
Street	
209 SE Dayton	
City	State Zip
John Day	OR 97845
Latitude	Longitude
44.41447	118.95225
Tracking Code	Inspection Date
RVS in 2006	7/27/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


John Day Fire Department

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)




Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# John Day Fire Department

Gran\_fir05B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Plan Irregularity Secondary		N Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries