

Dayville School

Dayville SD 16J

Gran_sch03A

Building Type School	County Grant	
Street 285 School House Dr		
City Dayville	State OR	Zip 97825
Latitude 44.4675	Longitude 119.53773	
Tracking Code RVS in 2006	Inspection Date 7/26/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	0	-0.5	-0.4	0	-0.4	0	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dayville School

Final RVS Score

Final Type	Final Score
URM	2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Dayville School

Gran_sch03A

Enrollment 58	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1920
Total Area (square ft) 5825	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities None None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
S Elevation View	E Field Verified Year Built	SW Elevation View	
			
NE Plan Irregularity Primary	S Falling Hazard		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Dayville School

Dayville SD 16J

Gran_sch03B

Building Type	County	
School	Grant	
Street		
285 School House Dr		
City	State	Zip
Dayville	OR	97825
Latitude	Longitude	
44.46755	119.53806	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dayville School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Dayville School

Gran_sch03B

Enrollment 58	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1950	Est. Decade Built
Total Area (square ft) 5825	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Vertical Irregularity Primary		E Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Dayville School

Dayville SD 16J

Gran_sch03C

Building Type School	County Grant	
Street 285 School House Dr		
City Dayville	State OR	Zip 97825
Latitude 44.46737	Longitude 119.53841	
Tracking Code RVS in 2006	Inspection Date 7/26/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dayville School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Dayville School

Gran_sch03C

Enrollment 58	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1960
Total Area (square ft) 5825	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries