

Grant Union High School

John Day SD 3

Gran_sch05A

Building Type		County	
School		Grant	
Street			
911 S Canyon Blvd			
City	State	Zip	
John Day	OR	97845	
Latitude		Longitude	
44.40457		118.9482	
Tracking Code		Inspection Date	
RVS in 2006		7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Tertiary		0	0	0	0	0	0	0	0	0

Grant Union High School

Final RVS Score

Final Type

Final Score

C2

-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
275		1936	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82824	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: T shaped	Steps in Elevation View: Very Irregular Changes
Reentrant Corners: Other	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	Internal Discontinuous Diaphragm (large internal opening)

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Vertical Irregularity Primary

Grant Union High School

Gran_sch05B

John Day SD 3

Building Type		County	
School		Grant	
Street			
911 S Canyon Blvd			
City	State	Zip	
John Day	OR	97845	
Latitude		Longitude	
44.40428		118.9488	
Tracking Code		Inspection Date	
RVS in 2006		7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Tertiary	PC1	3.2	0	-0.5	0	0	0	-1	0	1.7

Grant Union High School

Final RVS Score

Final Type

Final Score

PC1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
275		1936	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82824	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:L shaped (Adjacent Build/Entity)	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Plan Irregularity Primary

Grant Union High School

Gran_sch05C

John Day SD 3

Building Type		County	
School		Grant	
Street			
911 S Canyon Blvd			
City	State	Zip	
John Day	OR	97845	
Latitude		Longitude	
44.40417		118.94845	
Tracking Code		Inspection Date	
RVS in 2006		7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Grant Union High School

Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
275		1936	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82824	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
Reentrant Corners: L Shaped	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Elevation View



Grant Union High School

John Day SD 3

Gran_sch05D

Building Type		County	
School		Grant	
Street			
911 S Canyon Blvd			
City	State	Zip	
John Day	OR	97845	
Latitude		Longitude	
44.40431		118.94814	
Tracking Code		Inspection Date	
RVS in 2006		7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Tertiary		0	0	0	0	0	0	0	0	0

Grant Union High School

Final RVS Score

Final Type

Final Score

RM1

-0.5

FEMA-154 Collapse Potential

Very High (100%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
275		1936	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82824	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Primary



Grant Union High School

John Day SD 3

Gran_sch05E

Building Type		County	
School		Grant	
Street			
911 S Canyon Blvd			
City		State	Zip
John Day		OR	97845
Latitude		Longitude	
44.40368		118.94854	
Tracking Code		Inspection Date	
RVS in 2006		7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Grant Union High School

Final RVS Score

Final Type

Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
275		1936	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82824	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	Steps in Elevation View: Single Change
Reentrant Corners: Other	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Vertical Irregularity Primary



SW Plan Irregularity Primary



SW Vertical Irregularity Primary

