

# Seneca Elementary School

John Day SD 3

Gran\_sch07A

Building Type School	County Grant	
Street 101 Park Ave		
City Seneca	State OR	Zip 97873
Latitude 44.13643	Longitude 118.97195	
Tracking Code RVS in 2006	Inspection Date 7/27/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Tertiary		0	0	0	0	0	0	0	0	0

Seneca Elementary School

### Final RVS Score

Final Type	Final Score
C2	-0.5

### FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Seneca Elementary School

Gran\_sch07A

Enrollment 61	Year Built (Field Verified) 1932	Year Built (Alt. Source) 1930	Est. Decade Built 1930
Total Area (square ft) 13674	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:U shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	

# Seneca Elementary School

John Day SD 3

Gran\_sch07B

Building Type School	County Grant	
Street 101 Park Ave		
City Seneca	State OR	Zip 97873
Latitude 44.13663	Longitude 118.97201	
Tracking Code RVS in 2006	Inspection Date 7/27/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	-0.4	0	0	-1.2	0	0
Secondary	RM1	3.6	-2	0	-0.4	0	0	-1.2	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seneca Elementary School

### Final RVS Score

Final Type	Final Score
C2	0

### FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Seneca Elementary School

Gran\_sch07B

Enrollment 61	Year Built (Field Verified) 1932	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 13674	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 W    Vertical Irregularity Primary		 N    Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Seneca Elementary School

John Day SD 3

Gran\_sch07C

Building Type School	County Grant	
Street 101 Park Ave		
City Seneca	State OR	Zip 97873
Latitude 44.13664	Longitude 118.97187	
Tracking Code RVS in 2006	Inspection Date 7/27/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	-1	0	2.3
Secondary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Tertiary		0	0	0	0	0	0	0	0	0

Seneca Elementary School

### Final RVS Score

Final Type	Final Score
W2	0.1

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Seneca Elementary School

Gran\_sch07C

Enrollment 61	Year Built (Field Verified) 1932	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 13674	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Steps in Elevation View: Single Change None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Vertical Irregularity Primary		 SE Vertical Irregularity Primary	
		 N Building Design Level	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries