

Crane Union High School

Harney County Union High SD 1J

Harn_sch01A

Building Type	County	
School	Harney	
Street		
43277 Crane-Venator Ln		
City	State	Zip
Crane	OR	97732
Latitude	Longitude	
43.41695	118.5756	
Tracking Code	Inspection Date	
RVS in 2006	6/29/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	0	0	-1.2	0	0.6
Secondary	S3	3.8	0	0	0	0	0	-1	0	2.8
Tertiary		0	0	0	0	0	0	0	0	0

Crane Union High School

Final RVS Score

Final Type	Final Score
W2	0.6

FEMA-154 Collapse Potential

High (>10%)



Oregon Geology

Crane Union High School

Harn_sch01A

Enrollment 84	Year Built (Field Verified) 1972	Year Built (Alt. Source) 1950	Est. Decade Built 1970
Total Area (square ft) 38432	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	

Crane Union High School

Harney County Union High SD 1J

Harn_sch01B

Building Type	County	
School	Harney	
Street		
43277 Crane-Venator Ln		
City	State	Zip
Crane	OR	97732
Latitude	Longitude	
43.41674	118.57484	
Tracking Code	Inspection Date	
RVS in 2006	6/29/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	0	-1	0	2.8
Secondary	W2	4.8	0	0	0	0	0	-1.2	0	3.6
Tertiary		0	0	0	0	0	0	0	0	0

Crane Union High School

Final RVS Score

Final Type	Final Score
S3	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Crane Union High School

Harn_sch01B

Enrollment 84	Year Built (Field Verified) 1972	Year Built (Alt. Source) 1950	Est. Decade Built 1970
Total Area (square ft) 38432	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crane Union High School

Harney County Union High SD 1J

Harn_sch01C

Building Type	County	
School	Harney	
Street		
43277 Crane-Venator Ln		
City	State	Zip
Crane	OR	97732
Latitude	Longitude	
43.41591	118.57509	
Tracking Code	Inspection Date	
RVS in 2006	6/29/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Crane Union High School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Crane Union High School

Harn_sch01C

Enrollment 84	Year Built (Field Verified) 1972	Year Built (Alt. Source) 1950	Est. Decade Built 1970
Total Area (square ft) 38432	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Primary Structural Type		 N Elevation View	
		 E Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries