

Hood River FD

City of Hood River

Hood_fir05A

| | | |
|--------------------|-----------------|-------|
| Building Type | County | |
| Fire - City | Hood | |
| Street | | |
| 1785 Meyer Parkway | | |
| City | State | Zip |
| Hood River | OR | 97031 |
| Latitude | Longitude | |
| 45.70304 | 121.52899 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 8/2/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 3.6 | -2 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | -0.1 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Hood River FD

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | -0.1 |

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|---|-----------------------------|--|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | 1986 | 1986 | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: T shaped | | Steps in Elevation View: Single Change | |
| Torsion: Eccentric Stiffness | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| Other: General | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| S | Elevation View | S | Falling Hazard |
|  | |  | |
| W | Elevation View | W | Elevation View |
|  | |  | |
| S | General Site | N | Elevation View |
|  | | | |
| S | General Site | | |

