

# Hood River Police

City of Hood River

Hood\_pol03A

Building Type Police - City	County Hood	
Street 211 2nd St		
City Hood River	State OR	Zip 97031
Latitude 45.70838	Longitude 121.51194	
Tracking Code RVS in 2006	Inspection Date 8/2/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	0	0	1
Secondary	C2	3.6	-2	-0.5	-0.4	0	0	0	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Hood River Police

### Final RVS Score

Final Type	Final Score
C2	0.7

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Hood River Police

Hood\_pol03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1920	1920	1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
Parapets: Unreinforced Across Front of Building		None	
Other: Brick Veneer		None	
			
E	Primary Structural Type	S	Elevation View
			
W	Elevation View	W	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Hood River Police

City of Hood River

Hood\_pol03B

Building Type	County	
Police - City	Hood	
Street		
211 2nd St		
City	State	Zip
Hood River	OR	97031
Latitude	Longitude	
45.70844	121.51175	
Tracking Code	Inspection Date	
RVS in 2006	8/2/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	0	0	3.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hood River Police

## Final RVS Score

Final Type	Final Score
RM1	3.1

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1920	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



W Elevation View

