

Riverside - Building A

Jack_coc01A

Rogue CC

Building Type		County	
Community_College		Jackson	
Street			
227 E. Ninth St			
City		State	Zip
Medford		OR	97501
Latitude		Longitude	
42.3252		122.86931	
Tracking Code		Inspection Date	
Miller 2004-05		7/25/2005	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverside - Building A

Final RVS Score

Final Type


Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1946	1946	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13980	2	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	None

Falling Hazards	Poor Conditions
Parapets: General	
None	
None	

