

# Riverside - (Wards) G Building

Jack\_coc03A

Rogue CC

Building Type		County	
Community_College		Jackson	
Street			
227 E. Ninth St			
City	State	Zip	
Medford	OR	97501	
Latitude		Longitude	
42.32565		122.87107	
Tracking Code		Inspection Date	
Miller 2004-05		7/25/2005	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	-0.4	0	-0.8	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverside - (Wards) G Building

## Final RVS Score

Final Type


Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1928	1928	1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
34125	2	Yes	No

Plan Irregularities	Vertical Irregularities
None	Yes: Unknown

Falling Hazards	Poor Conditions
Parapets: General	
None	
None	

