

Riverside - Building D

Jack_coc04A

Rogue CC

Building Type Community_College	County Jackson	
Street 117 S Central Ave		
City Medford	State OR	Zip 97501
Latitude 42.32644	Longitude 122.87043	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	0	0	0	-0.6	0	0	0.4
Secondary	C2	3.6	-2	0	0	0	-0.8	0	0	0.8
Tertiary		0	0	0	0	0	0	0	0	0


Riverside - Building D

Final RVS Score

Final Type	Final Score
C1	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Riverside - Building D

Jack_coc04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1968	1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
8673	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW	General Site	S	Primary Structural Type
			
N	Vertical Irregularity Primary	S	Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries