


Southern Oregon Regional Communications Center

Jackson County

Jack_eoc02A

Building Type	County
EOC-Public Safety Answering P	Jackson
Street	
10 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.32312	122.87781
Tracking Code	Inspection Date
RVS in 2006	7/6/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.9	-1.5	-0.5	-1.2	0	0	-0.6	0	-0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Southern Oregon Regional Communications Center

Final RVS Score

Final Type	Final Score
C1	-0.9

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Southern Oregon Regional Communications Center

Jack_eoc02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1932	1932	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	4	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
SE Elevation View		E Vertical Irregularity Primary	
			
S Other Joint to newer addition.		W Plan Irregularity Primary Plan Irregularity to the new addition can be seen to the right of the picture.	
E Falling Hazard			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries