

# Medford Fire Dept Station 3

Jack\_fir21A

City of Medford

Building Type	County
Fire - City	Jackson
Street	
530 Highland Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.32066	122.8502
Tracking Code	Inspection Date
RVS in 2006	7/6/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Medford Fire Dept Station 3

## Final RVS Score

Final Type	Final Score
RM1	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Medford Fire Dept Station 3

Jack\_fir21A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Plan Irregularity Primary Also shows vertical irregularity.		SE General Site	
		SW Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries