

# Medford Fire Dept Station 4

Jack\_fir22A

City of Medford

Building Type	County	
Fire - City	Jackson	
Street		
2208 Table Rock Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.35006	122.88207	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Medford Fire Dept Station 4

## Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1969	1969	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

  

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Out of Plane Lateral-Force-Resistance Elements	None
None	None

  

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Elevation View



N Field Verified Year Built