

Providence Medford Medical Center

Providence Health System - Oregon NFP

Jack_hos02A

Building Type	County	
Hospital	Jackson	
Street		
1111 Crater Lake Ave		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34011	122.8627	
Tracking Code	Inspection Date	
New Building	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3.2	0	-0.5	0	0	-0.6	0	0	2.1
Secondary	C3	3.4	0	-0.5	0	0	-0.6	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Providence Medford Medical Center

Final RVS Score

Final Type

Final Score

C1

2.1

FEMA-154 Collapse Potential

Low (<1%)



Providence Medford Medical Center

Jack_hos02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2005	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	4	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Elevation View		SW Vertical Irregularity Primary	
		NE Pounding Potential	

Providence Medford Medical Center

Providence Health System - Oregon NFP

Jack_hos02B

Building Type	County	
Hospital	Jackson	
Street		
1111 Crater Lake Ave		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.33923	122.86235	
Tracking Code	Inspection Date	
New Building	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	-0.5	0	1.8	-0.6	0	0	3.9
Secondary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Providence Medford Medical Center

Final RVS Score

Final Type

RM1

Final Score

2.3

FEMA-154 Collapse Potential

Low (<1%)



Providence Medford Medical Center

Jack_hos02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2005	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
SE Elevation View		E Pounding Potential	
			
SE General Site		S Plan Irregularity Primary Also shows vertical a irregularity.	
			
E Falling Hazard This metal overhead ornamental piece is not connected to the building.		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence Medford Medical Center

Providence Health System - Oregon NFP

Jack_hos02C

Building Type	County	
Hospital	Jackson	
Street		
1111 Crater Lake Ave		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.33951	122.86328	
Tracking Code	Inspection Date	
New Building	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S4	4	-2	-0.5	0	0	-0.8	0	0	0.7
Secondary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Tertiary		0	0	0	0	0	0	0	0	0

Providence Medford Medical Center

Final RVS Score

Final Type	Final Score
S4	0.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence Medford Medical Center

Jack_hos02C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2005	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	4	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
None		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Vertical Irregularity Primary		SE Primary Structural Type Shear wall underneath light metal.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries