

Rogue Valley Medical Center - Medford

Asante Health System NFP

Jack_hos03A

Building Type	County	
Hospital	Jackson	
Street		
2825 E Barnett Rd		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.31711	122.83042	
Tracking Code	Inspection Date	
New Building	7/17/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3.2	-2	-0.5	0	0	-0.6	0	0	0.1
Secondary	C2	4	-2	-0.5	0	0	-0.8	0	0	0.7
Tertiary	RM1	4	-2	-0.5	0	0	-0.8	0	0	0.7

Rogue Valley Medical Center - Medford

Final RVS Score

Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rogue Valley Medical Center - Medford

Jack_hos03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1958	2006	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
250000	5	Yes	No
Plan Irregularities		Vertical Irregularities	
Non-Parallel System		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Field Verified Year Built		S Plan Irregularity Primary	
		S Vertical Irregularity Primary	
		N General Site	
		NE General Site	
		N Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rogue Valley Medical Center - Medford

Asante Health System NFP

Jack_hos03B

Building Type	County	
Hospital	Jackson	
Street		
2825 E Barnett Rd		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.31731	122.83119	
Tracking Code	Inspection Date	
New Building	7/17/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3.2	-2	-0.5	0	0	-0.6	0	0	0.1
Secondary	C2	4	-2	-0.5	0	0	-0.8	0	0	0.7
Tertiary	RM1	4	-2	-0.5	0	0	-0.8	0	0	0.7

Rogue Valley Medical Center - Medford

Final RVS Score

Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rogue Valley Medical Center - Medford

Jack_hos03B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2006	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
250000	4	Yes	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Non-Parallel System		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rogue Valley Medical Center - Medford

Asante Health System NFP

Jack_hos03C

Building Type	County	
Hospital	Jackson	
Street		
2825 E Barnett Rd		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.31717	122.82977	
Tracking Code	Inspection Date	
New Building	7/17/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	-0.6	0	0	-0.1
Secondary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3

Rogue Valley Medical Center - Medford

Final RVS Score

Final Type	Final Score
C1	-0.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rogue Valley Medical Center - Medford

Jack_hos03C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2006	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
250000	3	Yes	No
Plan Irregularities		Vertical Irregularities	
Non-Parallel System		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Out of Plane Lateral-Force-Resistance Elements		None	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries