

# Ashland High School

Ashland SD 5

Jack\_sch07A

Building Type School	County Jackson	
Street 201 S Mountain Ave		
City Ashland	State OR	Zip 97520
Latitude 42.19067	Longitude 122.69956	
Tracking Code SER & RVS2006	Inspection Date 7/24/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

## Final RVS Score

Final Type	Final Score
RM1	2.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Ashland High School

Jack\_sch07A

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1960
Total Area (square ft) 238735	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
N Falling Hazard	N Field Verified Year Built		

# Ashland High School

Ashland SD 5

Jack\_sch07B

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19021	122.69951	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	-0.6	0	0	-0.1
Secondary	RM2	3.4	-1.5	-0.5	0	0	-0.6	0	0	0.8
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

## Final RVS Score

Final Type	Final Score
C1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Ashland High School

Jack\_sch07B

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1970
Total Area (square ft) 238735	Number of Stories 3	Basement	Pounding Potential No
<b>Plan Irregularities</b> Reentrant Corners: Other None None		<b>Vertical Irregularities</b> Building On Hill or Sloped Site None None	
<b>Falling Hazards</b> None None None		<b>Poor Conditions</b> None None None	
			
NW Primary Structural Type		SE Vertical Irregularity Primary 2 stories compared to 3 on the first image.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
 Oregon Department of Geology and Mineral Industries

# Ashland High School

Ashland SD 5

Jack\_sch07C

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19018	122.69999	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Jack\_sch07C

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 238735	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None Unreinforced Chimneys		Poor Conditions None None None	
			
N General Site		S Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Ashland SD 5

Jack\_sch07D

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19155	122.69962	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)
-------------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Jack\_sch07D

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 238735	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Non-Parallel System		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Vertical Irregularity Primary And secondary vertical.		S Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Ashland SD 5

Jack\_sch07E

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.1918	122.70013	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

## Final RVS Score

Final Type	Final Score
S3	2.7

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Ashland High School

Jack\_sch07E

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1980
Total Area (square ft) 238735	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Ashland SD 5

Jack\_sch07F

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19121	122.7008	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

## Final RVS Score

Final Type	Final Score
RM1	2.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Jack\_sch07F

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1970
Total Area (square ft) 238735	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

# Ashland High School

Ashland SD 5

Jack\_sch07G

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19066	122.70063	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

## Final RVS Score

Final Type	Final Score
RM1	0.3

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Jack\_sch07G

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 238735	Number of Stories 3	Basement	Pounding Potential No
<b>Plan Irregularities</b> Reentrant Corners: Other None None		<b>Vertical Irregularities</b> Building On Hill or Sloped Site Vertical Change in Structural Type (Soft over Stiff) None	
<b>Falling Hazards</b> None None None		<b>Poor Conditions</b> None None None	
			
W Plan Irregularity Primary	W Vertical Irregularity Primary 3 stories can be seen in this image.	E General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Ashland SD 5

Jack\_sch07H

Building Type	County	
School	Jackson	
Street		
201 S Mountain Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19096	122.70114	
Tracking Code	Inspection Date	
SER & RVS2006	7/24/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Ashland High School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ashland High School

Jack\_sch07H

Enrollment 1123	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1970
Total Area (square ft) 238735	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Plan Irregularity Primary		N Secondary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries