

Hanby Middle School

Central Point SD 6

Jack_sch13A

Building Type	County	
School	Jackson	
Street		
806 6th Ave		
City	State	Zip
Gold Hill	OR	97525
Latitude	Longitude	
42.43459	123.05476	
Tracking Code	Inspection Date	
RVS in 2006	7/19/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	0	-0.5	-0.4	0	-0.4	0	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hanby Middle School

Final RVS Score

Final Type	Final Score
URM	2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hanby Middle School

Jack_sch13A

Enrollment 275	Year Built (Field Verified) 1910	Year Built (Alt. Source) 1910	Est. Decade Built 1910
Total Area (square ft) 38449	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
E	Plan Irregularity Primary	S	Plan Irregularity Secondary
			
S	General Site	S	General Site
			
S	Falling Hazard	S	Falling Hazard



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hanby Middle School

Central Point SD 6

Jack_sch13B

Building Type	County
School	Jackson
Street	
806 6th Ave	
City	State Zip
Gold Hill	OR 97525
Latitude	Longitude
42.43464	123.05521
Tracking Code	Inspection Date
RVS in 2006	7/19/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hanby Middle School

Final RVS Score

Final Type	Final Score
W2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Hanby Middle School

Jack_sch13B

Enrollment 275	Year Built (Field Verified) 1910	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 38449	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Plan Irregularity Primary also shows sloped site.		W Vertical Irregularity Primary also shows reentrant corner.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hanby Middle School

Central Point SD 6

Jack_sch13C

Building Type	County	
School	Jackson	
Street		
806 6th Ave		
City	State	Zip
Gold Hill	OR	97525
Latitude	Longitude	
42.43462	123.05582	
Tracking Code	Inspection Date	
RVS in 2006	7/19/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	1.6	-0.2	0	0	6.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hanby Middle School

Final RVS Score

Final Type	Final Score
W1	6.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hanby Middle School

Jack_sch13C

Enrollment 275	Year Built (Field Verified) 1910	Year Built (Alt. Source) 1910	Est. Decade Built 1980
Total Area (square ft) 38449	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries