

Scenic Middle School

Central Point SD 6

Jack_sch14A

Building Type	County	
School	Jackson	
Street		
1955 Scenic Ave		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.38637	122.92203	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Scenic Middle School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Scenic Middle School

Jack_sch14A

Enrollment 823	Year Built (Field Verified) 1966	Year Built (Alt. Source) 1966	Est. Decade Built 1960
Total Area (square ft) 78792	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		None None None	
Falling Hazards		Poor Conditions	
None None None		None None None	
			
S	Plan Irregularity Primary	W	General Site
			
		E	Other Modular



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Scenic Middle School

Central Point SD 6

Jack_sch14B

Building Type	County	
School	Jackson	
Street		
1955 Scenic Ave		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.38635	122.92309	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Scenic Middle School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Scenic Middle School

Jack_sch14B

Enrollment 823	Year Built (Field Verified) 1966	Year Built (Alt. Source) 1966	Est. Decade Built 1960
Total Area (square ft) 78792	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary sloped site.			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Scenic Middle School

Central Point SD 6

Jack_sch14C

Building Type	County	
School	Jackson	
Street		
1955 Scenic Ave		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.38669	122.92315	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Scenic Middle School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Scenic Middle School

Jack_sch14C

Enrollment 823	Year Built (Field Verified) 1966	Year Built (Alt. Source) 1966	Est. Decade Built 1960
Total Area (square ft) 78792	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SE Plan Irregularity Primary Reentrant corner.		N General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries