

Crater High School

Central Point SD 6

Jack_sch15A

Building Type	County	
School	Jackson	
Street		
4410 Rogue Valley Blvd		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.37979	122.92179	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
W2	3.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Crater High School

Jack_sch15A

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 138718	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 NE General Site		 S General Site	
 S Plan Irregularity Primary		 W Field Verified Year Built	

Crater High School

Central Point SD 6

Jack_sch15B

Building Type School	County Jackson	
Street 4410 Rogue Valley Blvd		
City Central Point	State OR	Zip 97502
Latitude 42.38032	Longitude 122.92286	
Tracking Code RVS in 2006	Inspection Date 7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	0	0	0	-0.6	0	0	0.4
Secondary	C2	3.6	-2	0	0	0	-0.8	0	0	0.8
Tertiary	S3	3.8	0	0	0	0	-0.6	0	0	3.2

Crater High School

Final RVS Score

Final Type	Final Score
C1	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 138718	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site None None	
Falling Hazards None None None		Poor Conditions None None None	

Crater High School

Central Point SD 6

Jack_sch15C

Building Type	County
School	Jackson
Street	
4410 Rogue Valley Blvd	
City	State Zip
Central Point	OR 97502
Latitude	Longitude
42.38031	122.92191
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Jack_sch15C

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1940
Total Area (square ft) 138718	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
S Falling Hazard		S Vertical Irregularity Primary also shows reentrant corner	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Central Point SD 6

Jack_sch15D

Building Type	County	
School	Jackson	
Street		
4410 Rogue Valley Blvd		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.38064	122.92201	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Jack_sch15D

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1970
Total Area (square ft) 138718	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer		Poor Conditions None None None	



SW General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Central Point SD 6

Jack_sch15E

Building Type School	County Jackson	
Street 4410 Rogue Valley Blvd		
City Central Point	State OR	Zip 97502
Latitude 42.38038	Longitude 122.92128	
Tracking Code RVS in 2006	Inspection Date 7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Crater High School

Jack_sch15E

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1960
Total Area (square ft) 138718	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>SE Plan Irregularity Primary vertical also</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Central Point SD 6

Jack_sch15F

Building Type	County	
School	Jackson	
Street		
4410 Rogue Valley Blvd		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.38056	122.92129	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Crater High School

Jack_sch15F

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1494		1950	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
138718	1	No	No
Plan Irregularities		Vertical Irregularities	
Non-Parallel System		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Plan Irregularity Primary		NE Vertical Irregularity Primary also shows reentrant corner.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Central Point SD 6

Jack_sch15G

Building Type School	County Jackson	
Street 4410 Rogue Valley Blvd		
City Central Point	State OR	Zip 97502
Latitude 42.38012	Longitude 122.92112	
Tracking Code RVS in 2006	Inspection Date 7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Jack_sch15G

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1980
Total Area (square ft) 138718	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Vertical Irregularity Primary		 W General Site also shows reentrant corners and vertical irregularity.	
		 S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Crater High School

Central Point SD 6

Jack_sch15H

Building Type	County
School	Jackson
Street	
4410 Rogue Valley Blvd	
City	State Zip
Central Point	OR 97502
Latitude	Longitude
42.37913	122.92021
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crater High School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Crater High School

Jack_sch15H

Enrollment 1494	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1960
Total Area (square ft) 138718	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



N Plan Irregularity Secondary



E Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries