

# Rogue River High School

Rogue River SD 35

Jack\_sch22A

Building Type	County
School	Jackson
Street	
1898 E Evans Creek Rd	
City	State Zip
Rogue River	OR 97537
Latitude	Longitude
42.45616	123.16812
Tracking Code	Inspection Date
RVS in 2006	7/19/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rogue River High School

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Rogue River High School

Jack\_sch22A

Enrollment 436	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1975	Est. Decade Built 1970
Total Area (square ft) 77578	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW General Site		W General Site	

# Rogue River High School

Rogue River SD 35

Jack\_sch22B

Building Type School	County Jackson	
Street 1898 E Evans Creek Rd		
City Rogue River	State OR	Zip 97537
Latitude 42.45595	Longitude 123.16706	
Tracking Code RVS in 2006	Inspection Date 7/19/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rogue River High School

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Rogue River High School

Jack\_sch22B

Enrollment 436	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 77578	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries